

Transition EIS: Preliminary Alternative 2

Area 18a - Well and Road Mitigations

Well No.	Area No.	Well Concerns	Mitigation
2283	18a	Is visible from North Country Scenic Trail	Provide vegetative screening
2317	18a	Is visible from North Country Scenic Trail	Provide vegetative screening
M166-2292	18a	Is visible from North Country Scenic Trail	Provide vegetative screening
M167-2272	18a	Wide seep	Moved well 50' south
M167-2288	18a	Spring and seeps	Moved well 50' southwest
M167-2288	18a	Fell within 100' of a seep	Avoid direct runoff into seep; follow appropriate best management practices
M191-2274	18a	Seep	Moved well southeast
M191-2274	18a	Is visible from North Country Scenic Trail	Moved well southeast; Provide vegetative screening
M191-2278	18a	Steep sideslopes	Moved well 50' southwest
M191-2279	18a	Is visible from North Country Scenic Trail	Moved well east to existing road corridor
M191-2280	18a	Close to North Country Trail; Steep sideslope; Rocks	Moved well 100' northwest
M191-2280	18a	Is visible from North Country Scenic Trail	Provide vegetative screening
M191-2284	18a	Is visible from North Country Scenic Trail	Moved well east; Provide vegetative screening
M191-2285	18a	Seeps	Moved well 45' southwest
M191-2285	18a	Fell within 100' of a seep	Moved southeast
M192-2265	18a	Wet area and seep	Moved well 50' southwest
M192-2265	18a	Is visible from North Country Scenic Trail	Provide vegetative screening
M192-2266	18a	Fell within 300ft of a concern level two travelway	Provide vegetative screening
M192-2268	18a	Fell within 300ft of a concern level two travelway	Provide vegetative screening
M192-2269	18a	Large flagged red oak near well stake	Moved well 50' north

Road No.	Area No.	Road Concerns	Mitigation
TE100012	18a	Fell within 50' of an intermittent stream	Crossing; Apply best management practices
TE102071	18a	Fell within 100' of a seep	Moved road west to edge of buffer